

SERVICE ALERT

Andair Ltd.,
Unit 15 The Tanneries,
Brockhampton Lane,
HAVANT,
Hampshire P091JB
UK.

1st Issued June 2010

Female fitting holding screws SERVICE ALERT

This Service Alert only applies to Andair Fuel Selector Valves and Andair Gascolators that have been supplied with female fittings and EF20/EF25 elbow fittings. This DOES NOT apply to valves and gascolators that were supplied with male AN6, AN8 any hose fitting or Banjo fitting.

It has been brought to our attention that the four holding screws that attach the fitting to the body unit (valve or gascolator) which are Stainless Steel M3 x 10 mm long countersunk hexagon head have not always been secured properly and in two cases have 'backed out'

This alert is issued for the inspection of these Countersunk screws. The inspector must be assured that these screws holding the fitting to the unit are tight and either loctited or as Andair recommends the edge of the countersunk screw is damaged into the small hole adjacent to the countersink edge.

It is Andair's intention to continue to offer female fittings "loose" with a screw pack together with the appropriate Allen key indicating how to secure the countersunk screws. This has been found to be of great benefit to builders when installing fittings such as the AN823 or AN816.

This SA will be issued to all customers that our records show have had selector valves and gascolators with female fittings and will be displayed on our web site

www.andair.co.uk

contact e-mail: andair@andair.co.uk

Telephone No: 01144 (0) 2392 473945

Fax No: (0) 2392 473946

Andair Fuel Selector Valve Service Alert



Andair Ltd. has issued a Service Alert for the Andair Fuel Selector Valves and Gascolators supplied with EF20/EF25 female fittings. Builders should inspect the stainless steel screws holding the female fittings to the fuel selector valve body to ensure they are tight and properly secured to prevent them from backing out. See the attached letter from Andair Ltd. for more information.

